# BBB ARCHITECTS ACTON OSTRY ARCHITECTS




# Design Permit Re-submission | NATIONAL SOCCER DEVELOPMENT CENTRE


9 March 2016



## **BBB** ARCHITECTS ACTON OSTRY ARCHITECTS

- exposed board form architectural concrete
- 1x8 rough sawn cedar shiplap siding (vertical)
- 2x4 rough sawn cedar siding (horizontal)
- rough sawn cedar fascia
- low anodized curtain wall glazing (typical of exterior)
- welded wire mesh guardrail (typical at stairs and ramps)
- chain link fence (black with screen)
- rooftop frame / screen





north elevation

### NOTE:

extent of rooftop screening to be determined upon installation of rooftop mechanical units

Campus & Community Planning University of British Columbia March 16/16








# **BBB** ARCHITECTS ACTON OSTRY ARCHITECTS

- exposed board form architectural concrete
- 1x8 rough sawn cedar shiplap siding (vertical)
- 2x4 rough sawn cedar siding (horizontal)
- rough sawn cedar fascia
- low anodized curtain wall giazing (typical of exterior)
- welded wire mesh guardrail (typical at stairs and ramps)
- chain link fence (black with screen)
- rooftop frame / screen



east elevation



• extent of rooftop screening to be determined upon installation of rooftop mechanical units

**Elevations** Design Permit Re-submission | NATIONAL SOCCER DEVELOPMENT CENTRE 9 March 2016





- exposed board form architectural concrete
- 1x8 rough sawn cedar shipiap siding (verticai)
- 2x4 rough sawn cedar siding (horizontal)
- rough sawn cedar fascia

- low anodized curtain wall glazing (typical of exterior)
- welded wire mesh guardrail (typical at stairs and ramps)
- chain link fence (black with
- rooftop frame / screen



view looking south from WFC natural turf training fields

### NOTE:

• extent of rooftop screening to be determined upon installation of rooftop mechanical units

Campus & Community Planning University of British Columbia







- exposed board form architectural concrete
- low anodized curtain wall glazing (typical of exterior)
- 1x8 rough sawn cedar shiplap siding (vertical)
- welded wire mesh guardrail (typical at stairs and ramps)
- 2x4 rough sawn cedar siding (horizontal)
- chain link fence (black with
- 4 rough sawn cedar fascia
- B rooftop frame / screen



view looking north-east from Rasphal Dhillon track + field oval

### NOTE:

extent of rooftop screening to be determined upon installation of rooftop mechanical units





- exposed board form architectural concrete
- 1x8 rough sawn cedar shiplap siding (vertical)
- 2x4 rough sawn cedar siding (horizontal)
- rough sawn cedar fascia

- iow anodized curtain wall glazing (typical of exterior)
- welded wire mesh guardrall (typical at stairs and ramps)
- chain link fence (black with
- rooftop frame / screen




view looking north from Thunderbird plaza



9 March 2016

- exposed board form architectural concrete
- 1x8 rough sawn cedar shiplap siding (vertical)
- 2x4 rough sawn cedar siding (horizontal)
- rough sawn cedar fascia

- low anodized curtain wail glazing (typical of exterior)
- weided wire mesh guardrail (typical at stairs and ramps)
- chain link fence (black with
- rooftop frame / screen



view looking east from WFC synthetic turf field

Campus & Community Planning University of British Columbia

By:





- exposed board form architectural concrete
- 1x8 rough sawn cedar shiplap siding (vertical)
- 2x4 rough sawn cedar siding (horizontal)
- rough sawn cedar fascia

- low anodized curtain wail glazing (typical of exterior)
- welded wire mesh guardrall (typical at stairs and ramps)
- chain link fence (black with
- rooftop frame / screen



view looking south-east from Harold Wright field

Campus & Community Planning University of British Columbia

9 March 2016

